

PART - I

PERFORMA FOR THE SAFETY OF SCHOOL BUILDING

(To be filled by the Head of school/Institution)

- 1 Name of School CAMBRIDGE INTERNATIONAL SCHOOL
- 2 Location KATHAR, JALANDHAR
- 3 Plot Area 5.75 ACRES
- 4 Plinth Area 12500
- 5 Number of Storey 4
- 6 Year of construction of building 2014, 2019, 2020
- 7 If the building has been constructed under the Supervision of the Qualified Engineer, the following details may be given.
- a) Name of the Engineer with Qualification _____
- b) Address of the engineer N/A
- c) Detail of structural drawing used in the construction, if available N/A
- d) Name & Address of Architect with qualification _____
- 8 Whether the building has been constructed for the purpose of
- a) School YES
- b) Residential purpose and converted for use as a school NO
- 9 Material used for roofs
- a) R.C.C. slabs YES
- b) R.S. Joists & Battens NO
- c) Wooden Joints & Battens NO
- 10 Material used for walls
- a) Mud Mortar NO
- b) Cement Mortar YES
- c) Plaster
- i) Lime Mortar NO
- ii) Cement Mortar YES
- 11 Flooring
- a) Conglomerate YES
- b) Terrazo NO
- c) Brick Paving NO
- 12 A detailed drawing indicating dimensions of the rooms alongwith size and location of doors and windows. DETAILED DRAWING ATTACHED



Principal

Chairman

Cambridge International School Kathar
V. Koopur, Jalandhar Pin-144106

PART - II


(To be filled by the S.D.O. of the P.W.D. B & R Department)

Name of School:- Cambridge International School.

- a) I have visited the above mentioned school on 17/4/26 and I have visually inspection it from all angles of safety and I find it fit for normal use an a school buildings
- b) In case any addition/alteration or expansion and modification to this building in to be carried out, the same may be carried out, under the supervision of the technically qualified Engineer and this certificate may again be obtained after the completion from the undersigned.
- c) In case the building is effected by flood, or if there is settlement of walls/foundation or sagging of roofs etc. immediate inspection of the undersigned be arranged to check the stability and safety of the building.
- d) This building can be safely occupied for normal use upto (indicate year upto which it can be used) upto This buildg is verry safe for year 2026-27 (upto 31/05/2027)

Ref. No 10

Dated 20/04/2026


Sub Divisional Engineer,
Provincial Sub Division No. 2
PWD B & R Br. Jalandhar.

RECEIVED THE OFFICE

Cambridge International School
Jalandhar

ਦਫਤਰ ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ, ਪ੍ਰਾਤਕ ਉਪ ਮੰਡਲ ਨੰ. 2, ਲੋਕ ਨਿਰਮਾਣ ਵਿਭਾਗ ਭ ਤੇ ਮ ਸਾਖਾ ਜਲੰਧਰ

ਸੇਵਾ ਵਿਖੇ

Principal,
Cambridge International School,
kathar, Jalandhar

ਨੰਬਰ..

10

ਮਿਤੀ 20-04-2026

ਵਿਸ਼ਾ:

ਬਿਲਡਿੰਗ ਸੇਫਟੀ ਸਰਟੀਫਿਕੇਟ (Cambridge International School) ਜਾਰੀ ਕਰਨ ਸਬੰਧੀ।

ਹਵਾਲਾ:

ਆਪ ਜੀ ਦੇ ਸਕੂਲ ਦਾ ਪੱਤਰ ਨੰ CISK/26-27/13 ਮਿਤੀ 02.04.2026

ਉਪਰੋਕਤ ਵਿਸ਼ੇ ਅਧੀਨ ਪੱਤਰ ਰਾਹੀਂ ਭੇਜੇ ਗਏ ਬੇਨਤੀ ਪੱਤਰ ਦੇ ਸਬੰਧ ਵਿੱਚ ਨਿਮਨਹਸਤਾਖਰ ਦੇ ਦਫਤਰ ਦੇ


ਜੂਨੀਅਰ ਇੰਜੀਨੀਅਰ ਵੱਲੋਂ ਰਿਪੋਰਟ ਕੀਤੀ ਗਈ ਹੈ ਕਿ ਇਸ ਸਕੂਲ ਦੀ ਬਿਲਡਿੰਗ ਸੁਰੱਖਿਅਤ ਪਾਈ ਗਈ। ਆਪ ਨੂੰ ਸਕੂਲ ਬਿਲਡਿੰਗ

ਦਾ ਸੇਫਟੀ ਸਰਟੀਫਿਕੇਟ (valid up to 31/03/2026) ਨਾਲ ਨੱਥੀ ਕਰਕੇ ਅਗਲੇਰੀ ਕਾਰਵਾਈ ਲਈ ਭੇਜਿਆ ਜਾਂਦਾ ਹੈ। ਇਥੇ ਇਹ

ਵੀ ਜਿਕਰਯੋਗ ਹੈ ਕਿ ਬਿਲਡਿੰਗ ਦੇ ਫਾਇਰ ਸੇਫਟੀ ਸਰਟੀਫਿਕੇਟ ਰੀਨਿਊ ਕਰਵਾਕੇ ਇਸ ਦਫਤਰ ਨੂੰ ਸੂਚਿਤ ਕੀਤਾ ਜਾਵੇ। ਜੇਕਰ ~~ਕੋਈ~~

ਆਪ ਜੀ ਵੱਲੋਂ ਇਹ ਸਰਟੀਫਿਕੇਟ ਜਮ੍ਹਾਂ ਨਹੀਂ ਕਰਵਾਇਆ ਜਾਂਦਾ ਤਾਂ ਇਸ ਦੀ ਨਿਰੋਲ ਜਿੰਮੇਵਾਰੀ ਆਪ ਦੇ ਸਕੂਲ ਦੀ ਹੋਵੇਗੀ।

ਨੱਥੀ/ਬਿਲਡਿੰਗ ਸੇਫਟੀ ਸਰਟੀਫਿਕੇਟ
ਅਤੇ ਚਲਾਨ ਦੀ ਕਾਪੀ


ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ,
ਪ੍ਰਾਤਕ ਉਪ ਮੰਡਲ 2, ਲੋ: ਨਿ: ਵਿ:, ਭ ਤੇ ਮ ਸਾਖਾ,
ਪੁਰਾਣੀ ਬਾਰਾਦਰੀ, ਜਲੰਧਰ